

Installation Case Study 2017 Toyota Tacoma

Installed Items: Modular Universal Coil Spring Buffer UCSB1, UCSB4

IMPORTANT NORICE: IMPORTANT NORICE: INSTALLERS SHOULD APPLY COMMON AUTOMOTIVE SAFETY PRACTICES WHEN RAISING, LOWERING AND WORKING ON VEHICLES, ALWAYS WEARING SAFTY GLASSES, USING BOTH HYDRAULIC JACK AND JACK STAND DURING THE INSTALLATION. We recommend that this installation be done by a professional or person with auto mechanical knowledge.





